

Created On	6.4.2020
Completed	No

Passed	Blocked	Untested	Retest	Failed
100% (32/32)	0% (0/32)	0% (0/32)	0% (0/32)	0% (0/32)
Skipped	Error	Warning	Repeated	
0% (0/32)	0% (0/32)	0% (0/32)	0% (0/32)	

1. Smoke test

ID	Title	Defects	Assigned To	Tested By	Status
T20194305	Successful installation (manager running)		Vojtěch M.	Vojtěch M.	Passed
T20194309	Section New zone concept (Beta) is not seen (have to enable it in ini file)		Vojtěch M.	Vojtěch M.	Passed
T20194368	All supported devices: C1004, C2005, C300X-E, C8033, C8210, C1310-E, C1410		Vojtěch M.	Vojtěch M.	Passed
T20194306	In scanner - devices are saw with proper IP address		Vojtěch M.	Vojtěch M.	Passed
T20194307	It is possible to add Axis devices by start using Axis devices (in factory or not)		Vojtěch M.	Vojtěch M.	Passed
T20194308	It is possible create, rename, delete Playlist		Vojtěch M.	Vojtěch M.	Passed
T20194312	It is possible create, rename, delete radio		Vojtěch M.	Vojtěch M.	Passed
T20194313	It is possible create, rename, delete rtp source		Vojtěch M.	Vojtěch M.	Passed
T20194314	It is possible create, rename, delete voip input		Vojtěch M.	Vojtěch M.	Passed
T20194319	It is possible use C8033 as source		Vojtěch M.	Vojtěch M.	Passed
T20194320	It is possible use C8210 as source		Vojtěch M.	Vojtěch M.	Passed
T20194311	It is possible create, rename, delete session		Vojtěch M.	Vojtěch M.	Passed
T20194315	It is possible add, remove Playlist to session		Vojtěch M.	Vojtěch M.	Passed
T20194316	It is possible add, remove radio to session		Vojtěch M.	Vojtěch M.	Passed
T20194317	It is possible add, remove rtp to session		Vojtěch M.	Vojtěch M.	Passed
T20194318	It is possible add, remove voip input to session		Vojtěch M.	Vojtěch M.	Passed
T20194321	It is possible add, remove C8033 to session		Vojtěch M.	Vojtěch M.	Passed
T20194322	It is possible add, remove C8210 to session		Vojtěch M.	Vojtěch M.	Passed
T20194323	Playlist plays about 5 minutes without crackling, delay,...		Vojtěch M.	Vojtěch M.	Passed
T20194324	Radio plays about 5 minutes without crackling, delay,...		Vojtěch M.	Vojtěch M.	Passed
T20194325	RTP plays about 5 minutes without crackling, delay,...		Vojtěch M.	Vojtěch M.	Passed
T20194326	Voip input plays without crackling, delay,...		Vojtěch M.	Vojtěch M.	Passed
T20194327	C8033 plays about 5 minutes without crackling, delay,...		Vojtěch M.	Vojtěch M.	Passed
T20194328	C8210 plays about 5 minutes without crackling, delay,...		Vojtěch M.	Vojtěch M.	Passed
T20194329	Create, rename, detele zone		Vojtěch M.	Vojtěch M.	Passed
T20194330	Put zone as destination to session		Vojtěch M.	Vojtěch M.	Passed

T20194331	Scheduler - create event (once only), activate session, start playing playlist, stop playing playlist, deactivate session	Vojtěch M.	Vojtěch M.	Passed
T20194332	Licences - devices are not connectet without licence (not for axis pc - there is unlimited licence)	Vojtěch M.	Vojtěch M.	Passed
T20194333	Possibility to choose primary interface (for multicast, scanner, ...)	Vojtěch M.	Vojtěch M.	Passed
T20194334	Possibility to add multicast address for playing	Vojtěch M.	Vojtěch M.	Passed
T20194335	Playing radio about 30 minutes via proxy without crackling, delay,....	Vojtěch M.	Vojtěch M.	Passed
T20194336	Add device in passive mode (Administrator -> Audio devices connections)	Vojtěch M.	Vojtěch M.	Passed